



- > Summary of all sectors arc and LSSs
- Leaks in 7-8 : K-C' in Q9R7 and D1/DFBX @ 8L
- > What remains ...
- >F 523 Contract

Work done by the whole MCS-IC section in collaboration with MCS-ET, MCS-SC, AT-MEL, AT-VAC, TS-IC, TS-SU,... and IEG (F523 Contract) and especially:

```
LSSs (Including triplets)

C Garion / I Slits

DFBL / Cryo ext /WRL

I Slits

Arcs

P Feesia, A Musso, M Struik, (1...8)

Reporting

O Denis
```





Sector	status	Next step
4-5	Cool down in progress ; T about 2.18 K	Power test
3-4	 Vacsec status a) Leak in 7R3 confirmed on K-C' circuit but in stand-by 1.5 10-6 mb I / sec (Use as is ?) b) Leak in 7L4 found after pressure test on jumper of DFBAG (See pictures from S Atieh – TS-MME) DSLC: Electrical interconnections completed LAST electrical test of an IC done with success (except 5L triplet and 8L) Welding of cryogenics lines in progress Waiting leak test (priority on 1-2) 	Jumper in repair
5-6	Cool-Down started	Cool-down

Ready for flushing


Flushing

6-7



Leak in jumper DFBA @ 4L









Sector	status	Next step
2-3	Pressure tested with success last week; Leak test on going with 10 bars He in cryolines	Repair of 6 Helium guards Cabling of one T sensor Leak localization and repair in 7L3
1-2	 All arc sectors are provided to VAC 4 still to be validated (priority) Activities on triplet 2L: Closure for end of W 47 Additional cryogenics instrumentation LSS1R: See V Parma (Done) – Q4/D2 reclosed Activities on triplet 1R: Repair of one PIM by AT-VAC to be tested 	Repair of He guards (7/11) Will be on critical path for pressure test (Bad vacuum) but no impact as PT of triplets is independent

NC 882743 Q2-Q3 R1








Sector status		Next step
7-8	Leak in DSR7 K-C' localised in jumper metal hose on QRL side; repair is on-going Triplet 8 L: Leak on CM circuit localised (see	Repair and local LT Repair of leak ?
	next slides)	
8-1	RAS	



Leak in K-C' at Q9R7 (1/2)










Leak in K-C' at Q9R7 (2/2)






- •Repair method defined and agreed between ACR and MCS Will be done by MCS-ET (19/11) Metal hose will be replaced with special adaptors to allow face welding
- •Spare provided by ACR (LHCDFB__0074) [PN 25] bar and tested by TS-MME (3 X LN2 shock + PT @ 25 bar; no leak > 3.2 10-10 mb I / sec) (20/11)
- Cut of leaking hose (20/11) by MCS
- Prepare adaptators (20/11) MCS
- Analysis of leaking hose (ACR)
- •Reweld and step by step leak test (MCS-VAC) (up to 26/11)
- •Reclosure of thermal shields and outside sleeve (MCS) (up to 28/11)
- Leak Test of external envelope (VAC)

Schedule to be confirmed; never done before.



Leak in D1/DFBX @ 8L (1/2)







Leak in D1/DFBX @ 8L (2/2) Schedule



Day			
1	Cut the bellows (depends on replacing one)		
2	Unsolder busbars and remove leaking bellows		
	// Leak test of bellows after LN2 cold schocks		
3	Prepare extremities and insert replacing bellows		
4&5	Resolder busbars		
6	Electrical test and insulation		
7	Welding of cryogenic line		
8	Local leak test		
9&10	Closure of IC		

- Evolution of a leak on a flexible elements is unknown so risk is high
- RHIC bellows is on his way to CERN; start tomorrow for day 1 after confirmation of reception
- Back-up solution : 2 line E bellows
- Part of replacement time is hidden by the repair in Q9R7





What remains in 2007

- 2 closures in 3-4 after DSLC IC and repair of DFBA leak
- Repair of Helium guards (1-2, 2-3) mainly
- Triplets in 1R, 2L and 5L (Low priority)
- DSLC interconnections with DFBLC and DFBAF
- Leaks repairs.... <u>At several locations</u>; a lot of leak tests interleaved with the assembly/repair activities





F523 Contract

- * Extension up to April 2008 Activities in 2008 (in 4-5 mainly):
 - *Reconnection of triplet 5L
 - * Warm-up so possible openings and replacement of PIMs
- Induction soldering machines are functionally tested. Will be transferred to CERN
- Ultrasonic welding machines are under test
- Programme is established for all tooling and components