



3.36×10^{-9}

5 BAR

"PRESSURE X LINE"

P. ATM

"VACUUM X LINE"

3.71×10^{-9}

5.89×10^{-10}

3.56×10^{-10}

4.17×10^{-9}

0 10 20 30 40 50 60 70 80 90 100

26 BAR

"PRESSURE MEAS LINE"

P. ATM

ZB 597

5.89×10^{-10}

4.40×10^{-9}